

October 2012
70 mph straight-line winds



These pictures were taken awhile later. My son had removed the big round bales that he had set on the west and north side to protect the hoophouse from the winds. The west end and north west side had little damage, but perhaps a tree limb hit in the middle and that east end really took a lot of abuse after the wind got in. The plastic was torn so badly, and would have such pressure on it, that replacing it seemed the best course. The door required a lot of effort on my son's part to work again.



The strawbales set on the outside around the bottom of the hoophouse had helped keep it warmer. Used them again when we restinked the hoop house in March.



My bent door frame

October 2012



70 mph winds