



2. Welded 3/4 inch plate to the opposite end of the unit to use to bolt accessories to. Placed reinforcement gussets behind plated end on I-Beam to add additional support during operation of press under 30 tons of pressure. Fabricated an additional wedge attachment to be bolted to end plate with 3/4 inch bolts.