

<b>Baseline Infiltration Tests 5/26/16</b>	<b>1:01</b>	<b>1:02</b>	<b>2:01</b>	<b>2:02</b>	<b>3:01</b>	<b>3:02</b>	<b>4:01</b>	<b>4:02</b>	<b>Notes</b>
E Pasture Control		6:05		30 minutes		33 minutes		60:00 +	4:02 took at least 10 minutes for initial water to drain
E Pasture Test		60:00 +		60:00 +		7:44		40 plus minutes	1:02 & 2:02 pulled up all the soil within the ring when ring was removed
Williams Control		5:07		8:15		10:40		8:39	
Williams Test		6:13		2:47		4:36		Rotted wet area closest to house.	Many snails & slugs in this field